


ASSEMBLY INSTRUCTIONS

TRANSACTION PEDESTAL RETURN



NOTE: Please count and inspect all pieces before disposing of any carton or packing materials.

COMPONENTS:



When ordering components, specific color and/or size information may be require
 Contact a Mayline Customer Service Representative. 1-800-822-8037

<u>REF. #</u>	<u>QTY.</u>	<u>DESCRIPTION</u>	<u>PART No.</u>
1	1	WORK SURFACE	CALL~~**
2	1	PEDESTAL	CALL**


** Denotes Color Code
 ~~Denotes Size

HARDWARE BAG (PART No. A8098) *for individual item, order that part number

<u>REF. #</u>	<u>QTY</u>	<u>DESCRIPTION</u>	<u>PART No.</u>
E1	21	#10 X 3/4 SCREW	X11*
E2	2	JOINING PLATE	B7522



1. Remove the Pedestal (2) from carton.
2. Remove all drawers from the Pedestal by pulling drawers out to the full extent. Locate the drawer slide release tab on each drawer slide. Press DOWN on the Right tab and LIFT the Left tab. Pull drawer forward to remove.





3. Turn the Pedestal upside down and install four Glides into threaded holes on bottom of Pedestal.

(1)

Assemble as shown for LEFT HAND Pedestal

4. Place the Work Surface (1) face down onto a clean, protected surface.
5. Position Pedestal (2) approximately 3/16" from the edges and align the Pedestal holes with the pre-drilled holes in the Work Surface (NOTE: DO NOT USE keyhole slots). Attach the Pedestal to Work Surface with four Screws (E1).





6. Align the holes in the two Joining Plates (E2) with the pre-drilled holes in the underside of the Adjacent table Work Surface. Attach each Joining Plate (E2) using four Screws (E1).

7. Place the assembled Return in the upright position. MAYLINE recommends that a minimum of two people perform this task.

8. Lay the assembled Return onto the Joining Plates (E2). Align the pre-drilled holes in the underside of the Return with the slots in the Joining Plates (E2) and secure the Return in place with four Screws (E1).

9. Level the assembly by adjusting all glides.

10. Return all drawers to the pedestal at this time.